Reporting committee: MEASUREMENT COMMITTEE

MAST MEASUREMENT CONDITIONS

PROPOSAL

Clarify mast measurement condition in IMS F8.

RATIONALE

IMS F8 is unclear in a few areas of mast conditions and set-up:

- (1) confirm that internally installed mast jacks should be included in the measurement of MWT and MCG because they are permanently installed in the spar.
- (2) confirm that checkstays/deflectors are also included in MWT and MCG since they are often internal to the spar and difficult to remove for measurement.